

TEST REPORT

5001 East Philadelphia Street Ontario, California – USA 91761-2816

Ph: 909.472.4100 | Fax: 909.472.4243 http://www.iapmortl.org

Report Number: 1554-15003

Report Issued: June 24, 2015 **Project No.:** 24772

Client: Green Drain, Inc.

335 North Puente Street # F

Brea, CA 92821 Contact: Ben Wilson

Source of Samples: The samples were shipped to IAPMO R&T Lab from Green Drain, Inc., and

received in good condition on April 02, 2015, and May 18, 2015.

Date of Testing: May 18, 2015 to June 23, 2015.

Sample Description: Trap Seal Devices

Models: *GD-102 (2")

GD-103 (3")

GD-103-5 (3.5")

*GD-104 (4")

"*" = tested samples.

Scope of Testing: The purpose of the testing was to determine whether the samples of the Trap Seal

Devices met the applicable requirements of ASSE Standard # 1072-2007, "Barrier

Type Floor Drain Trap Seal Protection Devices".

Conclusion: The samples tested of the Trap Seal Devices from Green Drain, Inc., models

as shown above, complied with the applicable requirements of ASSE 1072-

2007.

By our signatures below, we certify that all the testing and sample preparation for this report was performed under continuous, direct supervision of IAPMO R&T Lab, unless otherwise stated.

Tested By, Reviewed by,

Frank Lopez, Test Technician

Sean Vuu, P.E., Specialty Projects Manager

rean Vun

Primary Standards: ASSE Standard # 1072-2007 / Section tested:

- 1. General
- 2. Test Specimens
- 3. Performance Requirements and Compliance Testing
- 4. Detailed Requirements

Test Results: All tests and evaluations were conducted per the written procedures specified in the ASSE Standard # 1072-2007.

ASSE Standard # 1072-2007:

- 1.2 Scope:
- 1.2.1 Description FOLLOWED

The devices consisted of a membrane that allowed the flow of drainage to enter the plumbing drainage system. The devices closed when there was no flow.

1.2.2 Size – COMPLIED

The devices were sized according to the outlet sizes of the floor drains (2", 3", 3.5" and 4").

1.2.3 Flow Capacity – COMPLIED

The devices permitted the flows of drainage as stipulated in Table 1 of this standard (refer to section 3.1).

1.2.4 Rating – FOLLOWED

The devices were rated for the type of floor or floor finish in which the floor drain can be installed "AF-GW".

- 1.3 Construction COMPLIED
- 1.3.1 Function: the devices opened when there is a maximum of 4 oz of water on the inlet to the device, and closed when there was no flow of wastewater into the devices (refer to section 3.4).
- 1.3.2 Evaporation: the devices passed the evaporation test described in Section 3.2 of this standard.
- 1.3.3 Obstruction of Flow: to prevent the collection of waste solids, the opening passageways in the device did not have any sharp edges or protrusions which would obstruct the flow to the drainage system or result in stoppages. The devices did not obstruct access to the interior of the floor drain trap.
- 1.3.4 Connections Within Floor Drain: the device connected within a floor drain that conformed to ANSI/ASME A112.6.3.
- 2.0 Test Specimens:

Report No.: 1554-15003 Page 2 of 5

2.1 Sample Submitted – FOLLOWED

6 devices of each size and model were submitted by the manufacturer.

2.2 Samples Tested – FOLLOWED

1 sample was selected to be tested in order to sections 3.1 through 3.7 and additional 1 sample was selected to be tested to section 3.2, and another 1 sample was selected to be tested to section 3.8 of this standard.

2.3 Drawings – FOLLOWED

Assembly drawings, installation drawings, and other data which were necessary to enable the testing agency to determine compliance with this standard were accompanied assemblies when submitted for examination and performance testing under this standard.

2.4 Rejections – FOLLOWED

Failure of 1 device being tested shall be cause for rejection of that type or model and size.

3.0 Performance Requirements and Compliance Testing

3.1 Flow Test – COMPLIED

When tested to section 3.1.2 of this standard, the trap seals were able to flow at 12 gpm (2") and 73 gpm (4") for 10 minutes without overflowing the open sides of the pans.

3.2 Evaporation Test – COMPLIED

When tested to section 3.2.2 of this standard for 96 hours at 100°F, 20% relative humidity, the weight loss in cylinder A: 70.41g (2"), 269.9g (4"), cylinder B: 2.64g (2"; 3.75% of cylinder A), 7.8g (4"; 2.89% of cylinder A), cylinder C: 1.47 g (2"), 3.3g (4").

3.3 Trap Seal Interference Test – COMPLIED

When tested to section 3.3.2 of this standard, there was no protrusion of the device into the floor drain trap seal.

3.4 Opening Test – COMPLIED

When tested to section 3.4.2 of this standard, the devices started to open at: 1.31g (2"), and 2.2g (4").

3.5 Dirt and Debris Test – COMPLIED

When tested to section 3.5.2 of this standard, and subjected to section 3.2 for 96 hours, the weight loss in cylinder A: 75.42g (2"), 253.3g (4"), cylinder B: 2.53g (2"; 3.35% of cylinder A), 8.4g (4"; 3.32% of cylinder A), cylinder C: 1.44g (2"), 3.0g (4").

3.6 Floor Wax Test – COMPLIED

Report No.: 1554-15003 Page 3 of 5

When tested to section 3.6.2 of this standard at 1 GPM, the devices did not overflow the floor drain top grates.

3.7 Grease Test – COMPLIED

When tested to section 3.7.2 of this standard at 1 GPM, the devices did not overflow the floor drain top grates.

3.8 Life Cycle Test – COMPLIED

After tested to section 3.8.2 of this standard, and subjected to section 3.2 for 96 hours, the weight loss in cylinder A: 77.59g (2"), 290g (4"), cylinder B: 3.2g (2"; 4.12% of cylinder A), 9.7g (4"; 3.34% of cylinder A), cylinder C: 1.73 g (2"), 4.2g (4").

- 3.9 Physical Test of Membrane Material COMPLIED (refer to CRT report no.: 19741-S1).
- 4.1 Materials COMPLIED
- 4.1.1 Dissimilar Metals NOT APPLICABLE (no metal).
- 4.1.2 Internal Metallic Parts NOT APPLICABLE (no metal).

4.1.3 Non-metallic Parts - COMPLIED

Nonmetallic part (rubber & plastic) was designed for the rated operating temperature of the device without change in physical characteristics that would prevent full compliance with all requirements of this standard.

4.2.1 Marking of Devices – COMPLIED

Each device had the following information marked (molded), which is visible:

- a) Trademark "GREEN DRAIN" (per drawings).
- b) Application designation "AF-GW".

4.2.2 Packaging - COMPLIED

Each device had the following information marked (printed) on the packaging:

- a) Manufacturer's name "The Green Drain"
- b) Model number
- c) Rating for type of floor "AF-GW"
- d) Floor drain size.

4.3 Installation Instruction - COMPLIED

Instruction for installation of the device "press to install in drain outlet" was printed on the package.

Report No.: 1554-15003 Page 4 of 5







CRT LABORATORIES, INC.

1680 North Main Street, Orange, CA 92867

(714) 283-2032 • Fax (714) 283-1365

www.crtlabs.com • e-mail: crtlabs@crtlabs.com

ASTM Physical & Mechanical • Chemical-Thermal Analysis • IAPMO Cell Class Geosynthetic Materials • Plumbing & Faucet Assemblies • Resin & Finished Product Testing

TEST REPORT

PAGE 1 OF 2

FOR: IAPMO R & T Lab

5001 E. Philadelphia Street Ontario, CA 91761

Tel: (909) 472-4143 / Fax: (909) 472-4195

ATTN: Mr. Sean B. Vuu

LWR NO.: 19741-S1 DATE: June 22, 2015

BACKGROUND: The client submitted one (1) membrane material for testing to ASSE 1072-07

(Table 3). The sample arrived on 05/21/2015 via customer-supplied courier. Visual inspection was performed on 05/21/2015 and no product defects were noted. Testing in accordance with customer-supplied P.O. # 7339 received on

04/02/2015. The following additional information is provided:

CRT order entry log date: 05/21/2015 / Report due date: 06/22/2015

Sample ID: Membrane material (silicone) IAPMO Project # 24772

PREPARATION: Set-up, machining & die punching – CRT methods / ASTM methods

Chemical set-up & preparation – ASSE 1072-07 / CRT methods

Conditioning – ASTM D 618-13, 40 hours in a standard laboratory environment

SPECIFICATION: ASSE 1072-07(2013) Barrier Type Floor Drain Trap Seal Protection

Devices (Section 3.9 / Table-3 Physical Test of Membrane Material):

TEST PROCEDURES: Ozone resistance – ASTM D 1149-07, ASTM D 518 (method-B) at 104°F

(*2°F) for 100h at 150pphm

Water absorption – ASTM D 471-98 for 48 h 158°F ($^{\pm}2$ °F) Chemical Reagents – ASTM D 543-06 (72h at 74 \pm 3.6°F)

Weather-o-meter (500h) - ASTM G 154-12a (4h Q.U.V. @ 60°C / 4h

Condensation @ 50°C), U.V.B. 313 Bulbs

Tensile strength & Elongation – ASTM D 412-06a (Dumb-bell-C)

Split Tear strength – ASTM D 624-00 (Die-C)

Non-brittle Brittleness – ASTM D 2137-11 (3 minutes at -40°F (*2°F))

TEST RESULTS: The results of testing are shown in the attached data table.

CONCLUSION: Based on the results obtained, this sample meets the minimum requirements for

section 3.9 as described in ASSE 1072-07 (Table-3)... Complies

Specimen Retain Bin: BB (30 day hold only unless otherwise specified)

CRT LABORATORIES, INC.

IAPMO R&T SO 9001:2008 Certified - Registered / ISO-IEC 17025:2005 Accredited

Ken A. Le Jeune CEO / Laboratory Director Raul Gonzalez Laboratory Technician

The liability of CRT Labs with respect to the work and report covered herein, shall in no event exceed the amount of the invoice. We recommend consideration that correlative data be generated by other laboratories in matters of litigation. CRT will retain tested samples for 30 days after testing is completed, unless other arrangements are agreed upon at the time order is placed. This report, whether in whole or in part, any logo, etc., in advertising or publicity must have CRT's written permission prior to use. This test data is for exclusive use of the client to who it is addressed and results apply only to sample(s) tested and does not apply to similar or identical products. This report shall not be reproduced except in full. Testing performed in accordance with ISO 17025. Form Q.S. 43 (10/05)





CRT LABORATORIES, INC.

1680 North Main Street, Orange, CA 92867

(714) 283-2032 • Fax (714) 283-1365 www.crtlabs.com • e-mail: crtlabs@crtlabs.com

ASTM Physical & Mechanical • Chemical-Thermal Analysis • IAPMO Cell Class Geosynthetic Materials • Plumbing & Faucet Assemblies • Resin & Finished Product Testing TEST REPORT

PAGE 2 OF 2

FOR: IAPMO R & T Lab 5001 E. Philadelphia Street Ontario, CA 91761

Tel: (909) 472-4143 / Fax: (909) 472-4195 ATTN: Mr. Sean B. Vuu

RNO: 19741-S1 DATE June 22, 2015

TABLE 1


SAMPLE ID: Membrane material (silicone)
TESTING: Conformance to ASSE 1072-07 (Physical Test of Membrane Material)


IAPMO project #: 24772

RESULTS FROM TABLE-3 REQUIREMENTS


ASTM Method	Determination	Test values	Requirements
D 1149-07	(Method-B) Ozone resistance (visual) 150pphm / 40°C / 100h	No cracking or crazing / Pass	No cracking and/or crazing
D 471-06	Water absorption (%)	+ 0.36% / Pass	+ 20%, maximum
D 543-06	Chemical resistance (%) Sulfuric acid 1% (72h @ 23°C)	+ 0.17% / Pass	10%, maximum
D 543-06	Chemical resistance (%) Sodium hydroxide l% (72h @ 23°C)	+ 0.21% / Pass	10%, maximum
G 154-12a	UV Resistance	Specimens were exposed for 500 h using UVB 313 lamps	
D 412-06a	Initial Tensile strength (Psi)	853	N/A
D 412-06a	Initial Elongation (%)	656	N/A
D 412-06a	Change in Tensile strength (Psi)	(726) -17.49% / Pass	-50%, maximum
D 412-06a	Change in elongation (%)	(552) -15.85% / Pass	-50%, maximum
D 624-00	Split Tear strength at 23°C (kn/m)	23.38 / Pass	0.25 kn/m, minimum
D 2137-11	Brittleness @ -40°C	No brittleness / Pass	No brittleness


... Complies





N





Part number cross reference:

Green Drain, Inc.

Part Numbers

2" Drain GD-102
3" Drain GD-103
3.5" Drain GD-1035
4" Drain GD-104

Liquid Breaker, LLC

Part Numbers

2" Drain GD-102
3" Drain GD-103
3.5" Drain GD-1035
4" Drain GD-104

Jones Stephens Corporation

Part Numbers

2" Drain P24001
3" Drain P24002
3.5" Drain P24003
4" Drain P24004