

# Detailed Move In/Out Inspection

Seattle, WA, 98146

Inspected on May 31, 2019 8:05 AM

| Report Created on June 1, 2019 1:22 PM

## Overview

Inspection May 31, 2019

## General Information

Inspection May 31, 2019

Items	Values	Notes	Values	Notes
# of Keys	Apartment: 3			
# of Remotes	Apartment: 1			

## Entry

Inspection May 31, 2019

Items	Values	Notes	Values	Notes
Front Door	Good			
Walls	Good			
Windows	Good			
Flooring	Fair			
Lighting	Good			

## Living Room

Inspection May 31, 2019

Items	Values	Notes
Walls	Good	
Windows	Good	
Flooring	Good	
Baseboards	Good	
Lights	Good	

Values	Notes

## Kitchen

Inspection May 31, 2019

Items	Values	Notes
Walls	Good	
Windows	Good	
Flooring	Good	
Baseboards	Good	
Lights	Good	
Air Conditioning	Good	
Cabinets	Good	
Countertops	Good	
Pantry	Good	
Refrigerator	Good	
Oven	Good	
Stove Top	Good	
Exhaust Vent	Fair	
Sink / Faucet	Good	
Dishwasher	Good	
Tiling	Good	

Values	Notes

## Bedroom

Inspection May 31, 2019

Items	Values	Notes
Walls	Good	
Doors	Good	

Values	Notes

Items	Values	Notes
Windows	Good	
Flooring	Good	
Baseboards	Good	
Lights	Good	
Closet	Good	

Values	Notes

## Bathroom

Inspection May 31, 2019

Items	Values	Notes
Walls	Good	
Doors	Good	
Windows	Good	
Flooring	Good	
Lights	Good	
Cabinets	Good	
Towel Rack	Good	
Countertop	Good	
Shower	Good	
Shower Door	Good	
Bath	Good	
Mirror	Good	
Sink	Good	
Faucet	Good	
Exhaust Fan	Good	
Toilet Bowl	Good	
Toilet Seat	Good	
Toilet Paper Holder	Good	

Values	Notes

## Garage/Carport

Inspection May 31, 2019




# Signatures

A handwritten signature in black ink, appearing to be the initials 'ES'.


June 1, 2019 1:23 PM

A handwritten signature in black ink, appearing to be 'M. J. ...'.

June 1, 2019 1:23 PM

A handwritten signature in black ink, appearing to be 'G. W. ...'.

June 1, 2019 1:24 PM

A handwritten signature in black ink, appearing to be 'Ana Suzuki'.

Ana Suzuki

June 1, 2019 1:24 PM

---

# Photos

## Entry Photos




Front Door (1/4)  
05/31/2019 8:06 AM




Front Door (2/4)  
05/31/2019 8:06 AM




Front Door (3/4)  
05/31/2019 8:06 AM




Front Door (4/4)  
05/31/2019 8:06 AM



Walls (1/15)  
05/31/2019 8:16 AM



Walls (2/15)  
05/31/2019 8:16 AM




Walls (3/15)  
05/31/2019 8:16 AM



Walls (4/15)  
05/31/2019 8:16 AM



Walls (5/15)  
05/31/2019 8:16 AM



Walls (6/15)  
05/31/2019 8:16 AM




Walls (7/15)  
05/31/2019 8:16 AM



Walls (8/15)  
05/31/2019 8:22 AM




Walls (9/15)  
05/31/2019 8:22 AM



Walls (10/15)  
05/31/2019 8:22 AM



Walls (11/15)  
05/31/2019 8:22 AM



Walls (12/15)  
05/31/2019 8:26 AM


**Entry Photos**



Walls (13/15)  
05/31/2019 8:26 AM



Walls (14/15)  
05/31/2019 8:26 AM



Walls (15/15)  
05/31/2019 8:26 AM



Ceiling (1/13)  
06/01/2019 1:12 PM



Ceiling (2/13)  
06/01/2019 1:12 PM



Ceiling (3/13)  
06/01/2019 1:12 PM




Ceiling (4/13)  
06/01/2019 1:12 PM



Ceiling (5/13)  
06/01/2019 1:12 PM




Ceiling (6/13)  
06/01/2019 1:15 PM




Ceiling (7/13)  
06/01/2019 1:15 PM



Ceiling (8/13)  
06/01/2019 1:15 PM



Ceiling (9/13)  
06/01/2019 1:16 PM



Ceiling (10/13)  
06/01/2019 1:16 PM



Ceiling (11/13)  
06/01/2019 1:16 PM



Ceiling (12/13)  
06/01/2019 1:16 PM



Ceiling (13/13)  
06/01/2019 1:18 PM

**Entry Photos**



Windows (1/3)  
05/31/2019 8:27 AM



Windows (2/3)  
05/31/2019 8:27 AM



Windows (3/3)  
05/31/2019 8:27 AM



Flooring (1/5)  
05/31/2019 8:05 AM



Flooring (2/5)  
05/31/2019 8:05 AM



Flooring (3/5)  
05/31/2019 8:05 AM



Flooring (4/5)  
05/31/2019 8:05 AM



Flooring (5/5)  
05/31/2019 8:06 AM




Lighting  
05/31/2019 8:06 AM



**Living Room Photos**



Walls (1/8)  
05/31/2019 8:19 AM




Walls (2/8)  
05/31/2019 8:19 AM




Walls (3/8)  
05/31/2019 8:19 AM




Walls (4/8)  
05/31/2019 8:19 AM



Walls (5/8)  
05/31/2019 8:19 AM



Walls (6/8)  
05/31/2019 8:19 AM



Walls (7/8)  
05/31/2019 8:21 AM



Walls (8/8)  
05/31/2019 8:21 AM



Windows (1/4)  
05/31/2019 8:19 AM



Windows (2/4)  
05/31/2019 8:20 AM



Windows (3/4)  
05/31/2019 8:23 AM



Windows (4/4)  
05/31/2019 8:23 AM




Flooring (1/9)  
05/31/2019 8:20 AM



Flooring (2/9)  
05/31/2019 8:20 AM



Flooring (3/9)  
05/31/2019 8:20 AM




Flooring (4/9)  
05/31/2019 8:21 AM

## Living Room Photos



Flooring (5/9)  
05/31/2019 8:21 AM



Flooring (6/9)  
05/31/2019 8:21 AM



Flooring (7/9)  
05/31/2019 8:23 AM




Flooring (8/9)  
05/31/2019 8:23 AM



Flooring (9/9)  
05/31/2019 8:23 AM



Baseboards  
05/31/2019 8:21 AM




Lights (1/2)  
05/31/2019 8:21 AM



Lights (2/2)  
05/31/2019 8:21 AM


## Kitchen Photos




Walls (1/5)  
05/31/2019 8:08 AM




Walls (2/5)  
05/31/2019 8:08 AM



Walls (3/5)  
05/31/2019 8:08 AM



Walls (4/5)  
05/31/2019 8:08 AM




Walls (5/5)  
05/31/2019 8:08 AM



Windows (1/4)  
05/31/2019 8:08 AM



Windows (2/4)  
05/31/2019 8:08 AM



Windows (3/4)  
05/31/2019 8:08 AM

## Kitchen Photos



Windows (4/4)  
05/31/2019 8:09 AM



Flooring (1/3)  
05/31/2019 8:09 AM



Flooring (2/3)  
05/31/2019 8:09 AM



Flooring (3/3)  
05/31/2019 8:09 AM




Baseboards  
05/31/2019 8:09 AM



Lights (1/2)  
05/31/2019 8:09 AM



Lights (2/2)  
05/31/2019 8:09 AM



Air Conditioning  
05/31/2019 8:09 AM



Cabinets (1/4)  
05/31/2019 8:09 AM



Cabinets (2/4)  
05/31/2019 8:10 AM



Cabinets (3/4)  
05/31/2019 8:10 AM




Cabinets (4/4)  
05/31/2019 8:10 AM




Countertops (1/3)  
05/31/2019 8:10 AM



Countertops (2/3)  
05/31/2019 8:10 AM




Countertops (3/3)  
05/31/2019 8:10 AM



Pantry (1/5)  
05/31/2019 8:10 AM

**Kitchen Photos**



Pantry (2/5)  
05/31/2019 8:10 AM



Pantry (3/5)  
05/31/2019 8:10 AM



Pantry (4/5)  
05/31/2019 8:10 AM



Pantry (5/5)  
05/31/2019 8:10 AM



Refrigerator (1/5)  
05/31/2019 8:10 AM



Refrigerator (2/5)  
05/31/2019 8:10 AM



Refrigerator (3/5)  
05/31/2019 8:10 AM



Refrigerator (4/5)  
05/31/2019 8:11 AM



Refrigerator (5/5)  
05/31/2019 8:11 AM



Oven (1/2)  
05/31/2019 8:11 AM



Oven (2/2)  
05/31/2019 8:11 AM



Stove Top (1/2)  
05/31/2019 8:11 AM



Stove Top (2/2)  
05/31/2019 8:11 AM



Exhaust Vent  
05/31/2019 8:11 AM



Sink / Faucet (1/5)  
05/31/2019 8:11 AM



Sink / Faucet (2/5)  
05/31/2019 8:11 AM

**Kitchen Photos**



Sink / Faucet (3/5)  
05/31/2019 8:11 AM



Sink / Faucet (4/5)  
05/31/2019 8:11 AM



Sink / Faucet (5/5)  
05/31/2019 8:12 AM



Dishwasher (1/2)  
05/31/2019 8:12 AM



Dishwasher (2/2)  
05/31/2019 8:12 AM



Tiling (1/5)  
05/31/2019 8:12 AM




Tiling (2/5)  
05/31/2019 8:12 AM



Tiling (3/5)  
05/31/2019 8:12 AM



Tiling (4/5)  
05/31/2019 8:12 AM



Tiling (5/5)  
05/31/2019 8:13 AM

**Bedroom Photos**



Walls (1/16)  
05/31/2019 8:24 AM



Walls (2/16)  
05/31/2019 8:24 AM



Walls (3/16)  
05/31/2019 8:24 AM



Walls (4/16)  
05/31/2019 8:24 AM



Walls (5/16)  
05/31/2019 8:25 AM



Walls (6/16)  
05/31/2019 8:27 AM



Walls (7/16)  
05/31/2019 8:27 AM



Walls (8/16)  
05/31/2019 8:28 AM



Walls (9/16)  
05/31/2019 8:28 AM



Walls (10/16)  
05/31/2019 8:28 AM



Walls (11/16)  
05/31/2019 8:33 AM



Walls (12/16)  
05/31/2019 8:33 AM




Walls (13/16)  
05/31/2019 8:33 AM



Walls (14/16)  
05/31/2019 8:34 AM



Walls (15/16)  
05/31/2019 8:34 AM



Walls (16/16)  
05/31/2019 8:34 AM


**Bedroom Photos**




Doors (1/9)  
05/31/2019 8:24 AM



Doors (2/9)  
05/31/2019 8:24 AM



Doors (3/9)  
05/31/2019 8:24 AM



Doors (4/9)  
05/31/2019 8:27 AM




Doors (5/9)  
05/31/2019 8:27 AM



Doors (6/9)  
05/31/2019 8:27 AM



Doors (7/9)  
05/31/2019 8:34 AM



Doors (8/9)  
05/31/2019 8:34 AM



Doors (9/9)  
05/31/2019 8:34 AM



Windows (1/3)  
05/31/2019 8:25 AM



Windows (2/3)  
05/31/2019 8:28 AM



Windows (3/3)  
05/31/2019 8:34 AM




Flooring (1/16)  
05/31/2019 8:26 AM



Flooring (2/16)  
05/31/2019 8:26 AM



Flooring (3/16)  
05/31/2019 8:26 AM




Flooring (4/16)  
05/31/2019 8:26 AM

**Bedroom Photos**



Flooring (5/16)  
05/31/2019 8:26 AM



Flooring (6/16)  
05/31/2019 8:26 AM



Flooring (7/16)  
05/31/2019 8:29 AM



Flooring (8/16)  
05/31/2019 8:29 AM



Flooring (9/16)  
05/31/2019 8:29 AM



Flooring (10/16)  
05/31/2019 8:29 AM



Flooring (11/16)  
05/31/2019 8:34 AM



Flooring (12/16)  
05/31/2019 8:34 AM



Flooring (13/16)  
05/31/2019 8:34 AM




Flooring (14/16)  
05/31/2019 8:35 AM



Flooring (15/16)  
05/31/2019 8:35 AM



Flooring (16/16)  
05/31/2019 8:35 AM



Baseboards (1/3)  
05/31/2019 8:25 AM



Baseboards (2/3)  
05/31/2019 8:28 AM



Baseboards (3/3)  
05/31/2019 8:35 AM




Lights (1/3)  
05/31/2019 8:24 AM



**Bedroom Photos**



Lights (2/3)  
05/31/2019 8:28 AM



Lights (3/3)  
05/31/2019 8:35 AM




Closet (1/13)  
05/31/2019 8:25 AM




Closet (2/13)  
05/31/2019 8:25 AM



Closet (3/13)  
05/31/2019 8:28 AM



Closet (4/13)  
05/31/2019 8:35 AM



Closet (5/13)  
05/31/2019 8:35 AM



Closet (6/13)  
05/31/2019 8:35 AM



Closet (7/13)  
05/31/2019 8:36 AM




Closet (8/13)  
05/31/2019 8:36 AM




Closet (9/13)  
05/31/2019 8:36 AM




Closet (10/13)  
05/31/2019 8:36 AM



Closet (11/13)  
05/31/2019 8:36 AM



Closet (12/13)  
05/31/2019 8:36 AM




Closet (13/13)  
05/31/2019 8:36 AM

**Bathroom Photos**




Walls (1/16)  
05/31/2019 8:13 AM



Walls (2/16)  
05/31/2019 8:13 AM



Walls (3/16)  
05/31/2019 8:13 AM




Walls (4/16)  
05/31/2019 8:13 AM



Walls (5/16)  
05/31/2019 8:13 AM




Walls (6/16)  
05/31/2019 8:13 AM



Walls (7/16)  
05/31/2019 8:13 AM



Walls (8/16)  
05/31/2019 8:13 AM



Walls (9/16)  
05/31/2019 8:13 AM



Walls (10/16)  
05/31/2019 8:29 AM



Walls (11/16)  
05/31/2019 8:29 AM




Walls (12/16)  
05/31/2019 8:29 AM



Walls (13/16)  
05/31/2019 8:29 AM



Walls (14/16)  
05/31/2019 8:29 AM



Walls (15/16)  
05/31/2019 8:36 AM



Walls (16/16)  
05/31/2019 8:36 AM

**Bathroom Photos**



Doors (1/9)  
05/31/2019 8:15 AM



Doors (2/9)  
05/31/2019 8:15 AM



Doors (3/9)  
05/31/2019 8:15 AM



Doors (4/9)  
05/31/2019 8:30 AM




Doors (5/9)  
05/31/2019 8:30 AM




Doors (6/9)  
05/31/2019 8:30 AM



Doors (7/9)  
05/31/2019 8:33 AM



Doors (8/9)  
05/31/2019 8:36 AM



Doors (9/9)  
05/31/2019 8:36 AM



Windows (1/7)  
05/31/2019 8:13 AM




Windows (2/7)  
05/31/2019 8:13 AM



Windows (3/7)  
05/31/2019 8:13 AM



Windows (4/7)  
05/31/2019 8:13 AM



Windows (5/7)  
05/31/2019 8:30 AM



Windows (6/7)  
05/31/2019 8:39 AM



Windows (7/7)  
05/31/2019 8:39 AM

**Bathroom Photos**



Flooring (1/7)  
05/31/2019 8:14 AM



Flooring (2/7)  
05/31/2019 8:14 AM



Flooring (3/7)  
05/31/2019 8:30 AM



Flooring (4/7)  
05/31/2019 8:30 AM



Flooring (5/7)  
05/31/2019 8:30 AM



Flooring (6/7)  
05/31/2019 8:36 AM



Flooring (7/7)  
05/31/2019 8:36 AM



Lights (1/3)  
05/31/2019 8:15 AM



Lights (2/3)  
05/31/2019 8:30 AM



Lights (3/3)  
05/31/2019 8:37 AM



Cabinets (1/4)  
05/31/2019 8:15 AM



Cabinets (2/4)  
05/31/2019 8:30 AM



Cabinets (3/4)  
05/31/2019 8:37 AM



Cabinets (4/4)  
05/31/2019 8:37 AM



Towel Rack (1/3)  
05/31/2019 8:14 AM




Towel Rack (2/3)  
05/31/2019 8:31 AM

**Bathroom Photos**




Towel Rack (3/3)  
05/31/2019 8:37 AM



Countertop (1/8)  
05/31/2019 8:15 AM



Countertop (2/8)  
05/31/2019 8:15 AM



Countertop (3/8)  
05/31/2019 8:31 AM



Countertop (4/8)  
05/31/2019 8:31 AM



Countertop (5/8)  
05/31/2019 8:31 AM



Countertop (6/8)  
05/31/2019 8:37 AM



Countertop (7/8)  
05/31/2019 8:37 AM



Countertop (8/8)  
05/31/2019 8:37 AM



Shower (1/10)  
05/31/2019 8:31 AM




Shower (2/10)  
05/31/2019 8:31 AM



Shower (3/10)  
05/31/2019 8:31 AM



Shower (4/10)  
05/31/2019 8:31 AM



Shower (5/10)  
05/31/2019 8:40 AM



Shower (6/10)  
05/31/2019 8:40 AM



Shower (7/10)  
05/31/2019 8:40 AM

**Bathroom Photos**



Shower (8/10)  
05/31/2019 8:40 AM



Shower (9/10)  
05/31/2019 8:40 AM



Shower (10/10)  
05/31/2019 8:40 AM



Shower Door (1/6)  
05/31/2019 8:31 AM



Shower Door (2/6)  
05/31/2019 8:31 AM



Shower Door (3/6)  
05/31/2019 8:39 AM



Shower Door (4/6)  
05/31/2019 8:39 AM



Shower Door (5/6)  
05/31/2019 8:39 AM



Shower Door (6/6)  
05/31/2019 8:39 AM



Bath (1/9)  
05/31/2019 8:31 AM




Bath (2/9)  
05/31/2019 8:31 AM



Bath (3/9)  
05/31/2019 8:31 AM




Bath (4/9)  
05/31/2019 8:31 AM



Bath (5/9)  
05/31/2019 8:39 AM



Bath (6/9)  
05/31/2019 8:39 AM



Bath (7/9)  
05/31/2019 8:39 AM

**Bathroom Photos**




Bath (8/9)  
05/31/2019 8:39 AM



Bath (9/9)  
05/31/2019 8:39 AM



Mirror (1/7)  
05/31/2019 8:15 AM



Mirror (2/7)  
05/31/2019 8:15 AM



Mirror (3/7)  
05/31/2019 8:31 AM



Mirror (4/7)  
05/31/2019 8:31 AM



Mirror (5/7)  
05/31/2019 8:37 AM



Mirror (6/7)  
05/31/2019 8:38 AM



Mirror (7/7)  
05/31/2019 8:38 AM



Sink (1/3)  
05/31/2019 8:15 AM




Sink (2/3)  
05/31/2019 8:31 AM



Sink (3/3)  
05/31/2019 8:38 AM




Faucet (1/3)  
05/31/2019 8:15 AM



Faucet (2/3)  
05/31/2019 8:32 AM



Faucet (3/3)  
05/31/2019 8:38 AM



Exhaust Fan (1/3)  
05/31/2019 8:14 AM

**Bathroom Photos**



Exhaust Fan (2/3)  
05/31/2019 8:32 AM



Exhaust Fan (3/3)  
05/31/2019 8:38 AM



Toilet Bowl (1/6)  
05/31/2019 8:14 AM



Toilet Bowl (2/6)  
05/31/2019 8:14 AM



Toilet Bowl (3/6)  
05/31/2019 8:32 AM



Toilet Bowl (4/6)  
05/31/2019 8:32 AM



Toilet Bowl (5/6)  
05/31/2019 8:38 AM



Toilet Bowl (6/6)  
05/31/2019 8:38 AM



Toilet Seat (1/3)  
05/31/2019 8:14 AM



Toilet Seat (2/3)  
05/31/2019 8:32 AM



Toilet Seat (3/3)  
05/31/2019 8:38 AM



Toilet Paper Holder (1/3)  
05/31/2019 8:14 AM



Toilet Paper Holder (2/3)  
05/31/2019 8:32 AM



Toilet Paper Holder (3/3)  
05/31/2019 8:38 AM




**Garage/Carport Photos**



Walls (1/5)  
05/31/2019 8:17 AM



Walls (2/5)  
05/31/2019 8:17 AM



Walls (3/5)  
05/31/2019 8:17 AM



Walls (4/5)  
05/31/2019 8:17 AM



Walls (5/5)  
05/31/2019 8:17 AM



Ceiling (1/2)  
05/31/2019 8:17 AM



Ceiling (2/2)  
05/31/2019 8:17 AM



Flooring (1/4)  
05/31/2019 8:18 AM



Flooring (2/4)  
05/31/2019 8:18 AM




Flooring (3/4)  
05/31/2019 8:18 AM



Flooring (4/4)  
05/31/2019 8:18 AM




Lights (1/2)  
05/31/2019 8:18 AM



Lights (2/2)  
05/31/2019 8:18 AM



Garage Door (1/2)  
05/31/2019 8:18 AM



Garage Door (2/2)  
05/31/2019 8:18 AM

## Storage Area Photos



Walls (1/10)  
05/31/2019 8:22 AM



Walls (2/10)  
05/31/2019 8:22 AM



Walls (3/10)  
05/31/2019 8:22 AM



Walls (4/10)  
05/31/2019 8:22 AM



Walls (5/10)  
05/31/2019 8:22 AM



Walls (6/10)  
05/31/2019 8:22 AM



Walls (7/10)  
05/31/2019 8:33 AM




Walls (8/10)  
05/31/2019 8:33 AM



Walls (9/10)  
05/31/2019 8:33 AM



Walls (10/10)  
05/31/2019 8:33 AM




Doors (1/2)  
05/31/2019 8:21 AM



Doors (2/2)  
05/31/2019 8:21 AM



Flooring (1/3)  
05/31/2019 8:22 AM



Flooring (2/3)  
05/31/2019 8:22 AM



Flooring (3/3)  
05/31/2019 8:33 AM


**Mechanical Photos**



Water Heater (1/2)  
05/31/2019 8:17 AM



Water Heater (2/2)  
05/31/2019 8:17 AM



Furnace (1/3)  
05/31/2019 8:17 AM



Furnace (2/3)  
05/31/2019 8:17 AM



Furnace (3/3)  
05/31/2019 8:17 AM



Air Conditioner  
05/31/2019 8:27 AM



Washer (1/2)  
05/31/2019 8:16 AM




Washer (2/2)  
05/31/2019 8:16 AM



Dryer (1/2)  
05/31/2019 8:16 AM




Dryer (2/2)  
05/31/2019 8:16 AM



Smoke Detector (1/3)  
05/31/2019 8:24 AM



Smoke Detector (2/3)  
05/31/2019 8:28 AM



Smoke Detector (3/3)  
05/31/2019 8:35 AM



Fire Extinguisher  
05/31/2019 8:12 AM